


QUICK-RELEASE CLAWS

Quick release claw - Blanking plug



Min / Max operating pressure

0 / 10 bar

Min. / Max temperature

-5 / 60 °C

Part number	Dim. A (mm)	Dim. B (mm)
EXP BRE	57	30